



最下部の一段の石材を残して解体が完了した南祠堂

Dismantled Southern Sanctuary beside the lowest stones

西トップ遺跡南祠堂の解体 Dismantlement of the Southern Sanctuary, Western Prasat Top

2012年3月から開始した西トップ遺跡南祠堂の解体は、ついに最下段の石材を残して他のすべての石材の解体が終了しました。そして解体と同時並行でおこなわれた考古学的発掘により、南祠堂の詳細が明らかになりました。

2012年6月に南祠堂の西側（Mトレンチ）で試掘をおこなったとき、南祠堂にともなう基礎の痕跡は確認されませんでした。しかし2013年6月に南祠堂の南側（Nトレンチ）で試掘調査をおこなったところ、いったん地面を掘りくぼめ、内部を砂で埋め戻す「掘込地業」と呼ばれる基礎の痕跡がみつかりました。この「掘込地業」は他のアンコール遺跡の寺院のいくつかでも確認されていますが、西トップ寺院での存在が確認されたのは今回が初めてです。

右の図で示したのが想定される南祠堂の「掘込地業」の範囲です。西側では基壇の内側にあるため、Mトレンチの調査では確認できなかったものと考えられます。

「掘込地業」の内部の砂は、基壇の中の砂とほぼ同じものでした。すなわち南祠堂の内部にはこのような砂が詰まっていたことがわかりました。一見すると構造材として砂は脆弱なように思われるのですが、なぜ砂が選ばれたのかという理由はまだ明らかになっていません。

The dismantlement for repairing of the Southern Sanctuary, started in March 2012, has been completed except the series of the lowest stones of the platform. An archaeological excavation associated with the dismantlement revealed the detail information of the construction of the Southern Sanctuary.


We carried out excavation in the western side of the Southern Sanctuary in June 2012 (Trench M); however, no evidence of foundation associated with the Southern Sanctuary was found. In June 2013 we opened a trench in the southern side of the Southern Sanctuary (Trench N), then we revealed an evidence of foundation. The foundation was made in the way hereinafter described; first, a pit was dug, and then, the pit was filled by fine sand. Existence of this kind of foundation is widely recognized at the sites of Angkor area; however, this is the first time to be recognized at Western Prasat Top.

The figure (right) indicates the estimated extent of the foundation. Since the foundation is positioned inside of the western outline of the platform, it has not been recognized by the excavation of Trench M.

The sand filling inside the foundation is the same as the filling of the platform. Therefore the sand is used as a construction material of the Southern Sanctuary. It seems that sand is weak and not suitable for construction material. The reason why sand was used for construction has not been cleared yet.

南祠堂南側の N トレンチの様子（南東から）：明褐色に見える部分が「掘込地業」の内部に詰められた砂

N trench in the south of the Southern Sanctuary (from the southeast): the light-brown soils are the fillings of the foundation



南祠堂の平面図と想定される「掘込地業」の範囲（ピンク色で示した部分）

Plan of the Southern Sanctuary and the estimated extent of the foundation (indicated by pink)